



# **VE Gear**™



VE GEAR offers value-engineered turnout gear, certified to NFPA 1971 Standards, at a price that meets the needs of budget-conscious departments. It is fully equipped with the necessary options to ensure safe and functional performance. With VE Gear, you know you are getting tough, reliable gear that will not compromise protection.

### Overview

# **Key Features**

#### **Enhanced Fit Features**

- Free-Up Sleeve Design
- Angled Patch Coat Pocket (81/4" x 91/4")
- Semi-Bellow Pant Pocket (63/4" x 9")
- Integrated "Clean Flow" collar and throat tab

#### **Maximized Mobility Features**

- Coat closure systems
- All paired with hook and loop
- > 32" Coat -- Zipper under flap
- > 34" Coat -- Hooks and Dees outside flap
- Pant closure system
- > Hooks and Dees outside flap paired with military grade snaps

#### **All-Around Protection Features**

- Steam-Blocker Knee & Elbow pad
- ""X-Protect" Closure (34" Hook & Dee only)

#### **Proven Durability Features**

- Choice of leather or HYPALON® shoulder reinforcements
- Choice of leather or HYPALON® knee and cuff reinforcements
- Radio Pocket 9 x 3 1/2 x 2 inches on the left chest with single Mic Loop
- Offset Seams between each layer reduces abrasion
- Bar-tack reinforced stress points
- 3M<sup>TM</sup> Scotchlite<sup>TM</sup> 2" plain or 3" triple trim NFPA Standard Configuration

#### Recommended Industries/Use

Fire Protection

#### Hazards

Fire

#### Regulations

• - Certified to NFPA 1971 Standards - Current Edition

#### **Historical Brand**

Sperian

#### **Specifications**

CA 21144

MTE http://www.mte.gov.br/Empregador/segsau/Pesquisa/CA\_DET.asp? Link

vNRCAProc=21144&Equipamento=00&NOEquipamento=&Fabricante=00&NOFabricante=

#### **Technical Support**

CORPORATE HEADQUARTERS AMERICAS 900 Douglas Pike Smithfield, RI 02917 USA

CUSTOMER SERVICE AMERICAS 4200 St-Laurent Blvd, 6th floor Montreal, Quebec, H2W 2H2 Canada tel.: 1 (514) 282-0503 Fax: 1 (514) 282-8871

Toll free: 1800 563 0504

# **Gear Maintenance**

The 2008 Edition of NFPA 1851, the Standard on Selection, Care and Maintenance of Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting became effective June 24, 2007. You can find a copy of the standard on the NFPA web site at www.nfpa.org.

The most significant change coming out of this edition is the addition of a chapter on the verification of Independent Service Providers (ISP) by a third party lab. This will ensure that all ISP, performing repairs for the Fire Service meet a minimum requirement with the verification of their quality program, seam strength and moisture barrier sealing.

Minor repairs will still be allowed to be performed by unverified ISP but the list of minor repairs is limited to: 1) Small patches to outer shell, 2) Repairing stitches (Major A seam repairs less than one inch), 3) Replacement of hardware (except closure system), and 4) Re-closing the liner after complete inspection.

Click here to download the list of Verified ISP / Warranty Service Centers in the USA & Canada



For general inquiries 800.343.3411

View other Sperian Sites © 2010 Sperian Protection